Professional range

Red Gasket Maker



Wynn's Red Gasket Maker is a flexible high-temperature resistant, watertight filling and bonding material. It is a polysiloxane based product in a pressure cartridge for making seals and gaskets in a rapid and easy way.

Properties

- ✓ Is resistant to oils, transmission fluids, water, antifreeze, grease, smoke and hot toxic gases.
- ✓ Replaces cork, felt, paper and rubber gaskets.
- ✓ Withstands low temperatures up to -40°C (continuous) and high temperatures up to 260°C (continuous) and 300°C (intermittent).
- ✓ Does not harm catalytic converters and electronic sensors.
- ✓ Retorquing is not necessary after complete curing.
- ✓ No mixing required (single component).

Applications

- ✓ Ideal for replacing seals and gaskets of engine components (cylinder-head cover, transmission and oil crankcase, water pumps, thermostats), light fittings, heating installations, AC, bodywork, industrial ovens, cooking stoves, window seals and many other applications.
- ✓ The product is not suitable for replacing head gaskets nor for applications that require continuous immersion in petrol.
- ✓ Do not use in joints deeper than 10 mm.
- ✓ Avoid contact with solvent cleaners during cure.

Technical data

Appearance	: Non-sag red paste
Density	: 1,08
Temperature resistance	: -40 to +260°C (up to 300°C for short exposure)
Application temperature range	: +5 to +40°C

Industrieweg 10 D | 1785 AG Den Helder | The Netherlands | info@unishore.nl | +31 (0)223 768 213 unishore.nl

Directions



- Remove plastic tear-off lid (1).
- Remove cap from nozzle (2).
- Ensure that surfaces are clean, dry and grease free.
- Turn the top clockwise until you hear a click (3). Now turn further clockwise till stop to open trigger completely (4). Turn to **Max** for a thicker bead and to **Min** for a thinner bead (5).
- Apply the Gasket Maker by lightly pressing the trigger and drawing the bead along (6).
- Immediately assemble parts.
- Hand tighten until product begins to squeeze out around the flange.
- Allow to cure for one hour, then retighten ¼ to ½ turn.
- Gasket will skin over in one hour and fully cure in 24 hours.
- After use, wipe the nozzle clean and put back the cap (7).
- If product has cured in the nozzle, loosen nozzle and remove cured product.
- If the application is one in which the components are to be dismantled after the gasket has been made, apply the Gasket Maker normally, but spread a light coating of oil to the opposing face of the joint before bringing the two surfaces together.

Packaging

PN 10807 – 12x200 ml – FR/NL/DE

Industrieweg 10 D | 1785 AG Den Helder | The Netherlands | info@unishore.nl | +31 (0)223 768 213 unishore.nl